

We save / Wolf Group

www.penosil.com

Wolf Group Head Office Suur-Paala 10 13619 Tallinn Estonia

tel +372 605 9300 fax +372 605 9315 info@penosil.com

TECHNICAL DATA SHEET

PENOSIL White Filling Foam 267

One-component ready to use polyurethane strawfoam with diisocyanate monomer content below 0,1%. Suitable for various building applications, e.g. filling of holes, sealing of joints and penetrations, thermal and acoustic insulating. Adheres well to most materials like wood, concrete, stone, plaster, metal, PVC and polystyrene.

- Formula with very low (<0,1%) diisocyanate monomer content
- Enhanced UV resistance
- Low curing pressure
- Can be plastered and painted
- High thermal and acoustic insulation value
- No need for additional moistening

Fields of application

- Filling cracks and larger holes before plastering and painting
- Sealing e.g. ventilation, cable or pipe penetrations
- Thermal and sound insulation

Application instructions

Application conditions

Air temperature during use: +5 °C to +30 °C. Make sure the ambient temperature stays within this range until the foam has fully cured.

Can temperature during application: +5 °C to +25 °C, best results at +20 °C.

Surface preparation

Remove dust, loose particles and oil stains from the surfaces. Protect adjacent surfaces with paper, plastic film or other suitable material. If needed add additional shield outside for weather protection (against rain, wind, etc.).

Application method

Shake the can vigorously at least 20 times. Remove the cap. Hold the foam can in upright position with valve up. Screw the straw applicator tightly to the foam can valve. Hold the can upside down when extruding the foam. Foam output can be adjusted with the applicator trigger.

Fill joints up to approx. 60%, as the foam expands. In case of larger joints apply foam in several layers. Excess foam can be cut after it has fully cured.

Cleaning

Use Penosil Foam Cleaner to clean tools and surfaces from uncured foam. Hands and clothes can also be cleaned from uncured foam with Penosil Cleaning Wipes. Remove cured foam mechanically after softening with Penosil Foam Remover.

PENOSIL

We save / Wolf Group

www.penosil.com

Wolf Group Head Office Suur-Paala 10 13619 Tallinn Estonia

tel +372 605 9300 fax +372 605 9315 info@penosil.com

Technical data

Properties	Value	Unit
Tack free time (EN 17333-3)	2327	min
Cutting time (30 mm bead, EN 17333-3)	<75	min
Fully cured in joint, 3x5cm (+23 °C)	<48	h
Curing pressure (EN 17333-2, moistened surfaces)	<2	kPa
Post expansion (EN 17333-2)	<110	%
Density in joint, 3x10cm (WGM106)	2024	kg/m³
Dimensional stability (EN 17333-2, moistened surfaces)	<3	%
Temperature resistance of cured product	-50+70	°C
Fire resistance class (EN 13501-2)	F	
Fire class of cured foam (DIN 4102-1)	B3	
Tensile strength / elongation (EN 17333-4, moistened surfaces)	>95/40	kPa / %
Compression strength (EN 17333-4, moistened surfaces)	>15	kPa
Shear strength (EN 17333-4, moistened surfaces)	>65	kPa
Thermal conductivity (EN 12667, EN 17333-5)	0,034	W/(m·K)
Sound reduction index R _{st,w} (EN ISO 10140)	62	dB

The values specified were obtained at +23 °C and 50% relative humidity, unless otherwise specified. These values may vary depending on environmental factors such as temperature, moisture and type of substrates.

Technical classification and certificates

- EMICODE® EC 1 Plus very low emission
- French VOC class A+

Colour

White.

Package

650 ml aerosol can, content 500 ml, 12 pcs in a box.

Storage conditions and shelf life

Guaranteed shelf life is 12 months from production date if stored in an unopened packaging in a cool and dry place at +5 °C to +30 °C. Do not expose to temperature over +50°C, do not keep near heat sources or in direct sunlight. Store and transport in vertical position. Secure cans before transport.

Limitations

- PU foam lacks adhesion to Teflon, polyethylene and silicone surfaces.
- Cured foam is less sensitive to UV-light and direct sunlight than other conventional one-component polyurethane foams. It is recommended to cover the cured foam with suitable opaque sealant, filler, paint or other material to ensure lasting quality features. Do not cover before foam has fully cured.
- Though there is no need for additional moistening, the foam still needs air humidity for curing. Do
 not cover with materials preventing access of air humidity before the foam has completely cured.
- Please observe the expiration date!



www.penosil.com

Wolf Group Head Office Suur-Paala 10 13619 Tallinn Estonia

tel +372 605 9300 fax +372 605 9315 info@penosil.com

Safety regulations

Pressurized canister. Use only in well-ventilated areas. Do not smoke during application! Use protective gear when necessary. Keep out of the reach of children.

See label and safety data sheet (SDS) for more information.

Note: The instructions in the present documentation are based on tests carried out by the manufacturer and are presented in good faith. Due to variations in materials and substrates as well as the various application possibilities that are beyond our control, the manufacturer is not liable for the results achieved. In any case, it is recommended to test the product suitability at the place of application. Manufacturer reserves the right to modify products without prior notice.

This TDS replaces and supersedes all previous data sheets on the same product.